

Total Quality Management

TQM Quiz

An acceptance control chart has limits that are based on the specification limits for the product rather than limits which differentiate between random and assignable causes. Under which if the following circumstance should a QC manager consider using an

A- When the engineering tolerance on a dimension greatly exceeds the natural dispersion of the manufacturing process B- When the number of samples outside the current control chart limits become too costly and cumbersome to investigate C- When a process is subject to constant but stable tool wear

D- A and B

acceptance control chart?

E- A and C

- The practice of ceasing mass inspections and ending awards based on price is credited to:
 - A- Edward Deming
 - **B- Philip Crosby**
 - **C- Juran**
 - **D- Pareto**

- *For more Q&A click here to

 visit our question bank

 visit our question bank

 *Or Click here to take a free complete

 quiz with online certification
- Quality management deals with all of the following topics except:
 - A- Conformance to requirements / specifications
 - B- Satisfying the needs of the customer
 - C- Making products more desirable and luxurious
 - D- A and C
 - E-B and C

- The OC curve provides a measure of the _
 of the control chart
 - A- SensitivityB- Duality

- *For more Q&A click here to

 visit our question bank

 visit our question bank

 *Or Click here to take a free complete

 quiz with online certification
- Lots for acceptance sampling should be and _____ and ____ .
 - A- Homogeneous, Large
 - **B- Heterogeneous, Small**
 - C- Homogeneous, Small
 - **D- Heterogeneous, Large**

- The four phases of the Shewart cycle are:
 - A- Plan, Do, Scan, Implement
 - B- Plan, Act, Do, Control
 - C- Plan, Do, Check, Act,
 - D- Implement, Design, Control, Plan
- Process capability indices, Cp and Cpk, are:
 - **A- Productivity measures**
 - **B- Financial measures**
 - C- Quality measures
 - **D- Time measures**

- The taste of burgers across all McDonald outlets should be same. This is an example of _______.
 - A- Sensory critical to quality Characteristic
 - **B- Physical critical to Quality Characteristic**
 - **C- Time Orientation critical to Quality Characteristic**
 - D- None of the above
- 9 Most quality problems-----
 - A- originate in the quality department where the ultimate responsibility for quality rests
 - B- originate on the shop floor because of waste and product rework
 - C- are the result of management's lack of attention to potential quality improvement ideas
 - D- could be eliminated if shop supervisors monitored their workers more closely
 - E- A and B

10 Quality assurance

- A- refers to the prevention of product defects
- B- is an auditing function that provides feedback to the project team and client about the quality of output being produced
 C- is the technical process that includes the construction of control charts
 - which specify acceptability limits for conforming output
 - D- A and B
 - E-Band C
- A _____ chart can be used to identify the most frequently occurring defect.
 - A- Pareto
 - **B-Ishikawa**
 - **C- Histogram**
 - **D-Scatter**

13

Process capability ratio is expressed as:

- A- USL+LSL/6s
- B- USL-LSL/6s
 - C- USL-LSL/3s
 - D- USL-LSL/s

*For more Q&A click here to

visit our question bank

visit our question bank

*Or Click here to take a free complete

quiz with online certification

100% inspection for defects may be neither possible nor desirable, When is sampling for defects likely to be most useful?

- A- When destructive testing is required
- B- When the cost of 100% inspection is high
- C- When we believe there are not many defects
- D-A, B, and C
- E- A and B

- A main role of the project Champion is to:
 - A- Be a cheerleader for the team
 - B- Remove roadblocks
 - **C- Perform statistical analysis**
 - D- Develop the control plan
- A histogram ordered by frequency of occurrence that shows how many results were generated by each identified cause is:
 - **A- Statistical Histogram**
 - B- Juran Histogram
 - **C- Fishbone Diagram**
 - **D- Pareto Diagram**

- The key process input variables (KPIV) and key process output variables are developed during the _____ phase.
 - A- Define
 - **B- Analyze**
 - C- Measure

17

- **D-Improve**
- In 9001:2015, what does clause 7.2 relate to?
- A- Leadership and commitment
- B- Competence
 - **C- Documented information**
 - **D- Planning of changes**

- 18
- When planning the quality management system ISO 9001, organizations shall consider the issues and requirements referred to in 4.1 and 4.2 and determine the risks and opportunities that need to be addressed to;
 - A- give assurance that the quality management system can achieve its intended result(s)
 - **B- enhance desirable effects**
 - **C- achieve improvement**
- D- all of the above

- *For more Q&A click here to visit our question bank
- *Or Click here to take a free complete quiz with online certification

- 19
- Given L=3 and p=.03, estimate the sample size that can be used for construction of a p chart.
- A-534
- **B-321**
- C- 123
- D- 291 ((1-p)*L2/p gives us an estimate of sample size)

Which of the following document(s) is (are) included in the quality system?

- A- A quality policy
 - **B- Customer focus**
 - **C- Commitment**
 - D- All of the given options

*For more Q&A click here to

visit our question bank

visit our question bank

*Or Click here to take a free complete

quiz with online certification

IRGST.org

Find more Tests, Quiz, Exams

Area	Q&A	Free Quiz with certification
IQ	Click here	<u>Click here</u>
English	<u>Click here</u>	<u>Click here</u>
Computer Driving	<u>Click here</u>	<u>Click here</u>
Project Management	<u>Click here</u>	<u>Click here</u>
Communication Skills	<u>Click here</u>	<u>Click here</u>
TQM	<u>Click here</u>	<u>Click here</u>
Food Safety	<u>Click here</u>	<u>Click here</u>
HSE	<u>Click here</u>	<u>Click here</u>
Basic Science	<u>Click here</u>	Click here

Irgst.org